

Intellex® 3.1
TB_20030826
2003-Aug-26

AUDIO AND THE BAYFIELD MOTHERBOARD ON INTELLEX 3.1 PLATFORMS

Engineering has identified an inconsistency with the new Bayfield motherboards when using audio on the Intellex 3.1 platforms.

Problem:

All Intellex systems manufactured after August 21, 2003 are configured with the Bayfield motherboard. Due to changes in the motherboard's application interface, when using audio on an Intellex unit with the aforementioned motherboard, the MIC Boost button has changed its function to mute.

Solution:

Users are advised to only use the Gain Slider and not the MIC Boost if they are using a microphone. It is also highly recommended that a preamp be used in conjunction with the Line In input.

This issue will be corrected in the Multi-Language release of Intellex 3.1 software, which is currently due to release in the latter part of September 2003.

CONTINUOUS IMPROVEMENT STATEMENT

As with all processes defined by the American Dynamics Technical Services Group, this document is intended to be a work in progress. Further refinements and suggestions are welcome and should be sent in writing to the owner/author of this document as listed below.

Author/Owner

Joie Malinski
jmalinski@tycoint.com
Initial publication 2003-Aug-25

CONTACT INFORMATION

If you have any questions regarding this bulletin, please contact American Dynamics Technical Services at:

Toll Free: 800-507-6268, Option 2
International: 561-912-6259, Option 2
Fax: 845-624-7658
Email : adtechservices@tycoint.com.

Information furnished by American Dynamics is believed to be accurate and reliable. However, no responsibility is assumed by American Dynamics for its use, nor any infringements of other rights of third parties which may result from its use. No license is granted by implications or otherwise under any patent rights of American Dynamics.