



TAB Number: TB-00203-00-100518 Rev 02

ADACSNET Firmware Update to 2.00

Date Issued: 20 MONTH, 2010

Product	Software
ADACSNET	1.01

Issue

This technical bulletin addresses an issue reported in ADACSNET software version 1.01:

- When using the ADACSNET USB Sensornet module for camera control from Intellex, in some circumstances the module would lose connection to the Intellex. This would result in loss of camera control that could only be restored when the Intellex application was restarted.

Solution

To resolve this issue it will be necessary to update the Intellex to software version 4.3 software update 5 (build number 4.30.68.218) or higher and the ADACSNET firmware to 2.00 by downloading and installing the latest firmware update.

NOTE: Both the Intellex and ADACSNET have to be updated to resolve the issue.

WARNING: The new ADACSNET firmware version 2.00 is only compatible with Intellex software version 4.3 software update 5 (build number 4.30.68.218) or above. If you are using an Intellex below this version, the current ADACSNET firmware version 1.01 must be used.

We recommend that AD Utilities version 8.0 is used for the firmware upgrade on the ADACSNET. This version is compatible with ADACSNET firmware version 1.01 and 2.00. Visit http://www.americandynamics.net/support/downloads_20100521_ADACSNET_Utility.aspx if you need to download AD Utilities version 8.0.

Procedure

To update an ADACSNET that is running firmware version 1.01 visit, http://www.americandynamics.net/support/downloads_20100521_ADACSNET_Firmware.aspx and follow the instructions to download and install the latest 2.00 firmware update.

You must then update the Intellex software.

To update an Intellex that is running software version 4.3 visit, http://americandynamics.net/support/downloads_20100519_Intellex_v43_Patch.aspx and follow the instructions to download and install the latest software update.



Continuous Improvement Statement

As with all processes defined by the American Dynamics Technical Services Group, this document is intended to be a work in progress. Further refinements and suggestions are welcome and should be sent in writing to the e-mail address listed below.

Contact Address:

adbulletins@tycosp.com

Initial publication 20 May YY

Contact Information

If you have any questions regarding this bulletin, please contact American Dynamics Technical Services at:

Toll Free	800-507-6268, Option 2
International	561-912-6259, Option 2
Fax	450-444-2029
Email	adtechservices@tycoint.com

In Europe, contact Technical Services at:

EMEA AD Technical Support	+800 CALLTYCO or +800-2255 8926
Direct	+31 475 352 722
Fax	+31 475 352 725
UK only	+44 (08701-238 787)
France only	+33 (04 72 79 14 83)
Spain only	+900 (10 19 45)
Email	tfsemea.support@tycoint.com
Website	www.tycosafetyproducts-europe.com
Hours	09:00 – 18:00 CET

Information furnished by American Dynamics is believed to be accurate and reliable. However, no responsibility is assumed by American Dynamics for its use, nor any infringements of other rights of third parties which may result from its use. No license is granted by implications or otherwise under any patent rights of American Dynamics.
