

VIDEO SYSTEMS

Adding Intelligence to Video

SERVICE BULLETIN

Date: 07/16/02

Service Bulletin SB_071602

Subject: Intellex 2.4 Svideo to Composite "Pigtail"

Purpose: This bulletin identifies a potential issue with Intellex systems where the Svideo to composite "pigtail" is missing or lost at installation.

Issue: The current video card shipping with Intellex 2.4 systems does not have a standard composite video output. Intellex ships with an Svideo to composite "pigtail" to use with the Svideo output. During installation of the Intellex the "pigtail" may become lost, misplaced, or discarded with the packaging materials.

Preferred Solution: Find and immediately install the Svideo to composite "pigtail" when initially unpacking Intellex. This will ensure that the "pigtail" is not mistakenly misplaced.

Alternate Solution: Video can be outputted to a VCR or composite monitor via the Live/Playback composite (BNC Connector) output standard on Intellex.

Alternate Solution: In the event that the "pigtail" does become lost or misplaced, a replacement can be ordered directly from Radeon. The descriptions is:

CABLE 7900 Radeon Svideo to Composite Cable \$5.00 plus S&H.

This part can be ordered directly online at: www.ati.com

Information furnished by Tyco Video Systems is believed to be accurate and reliable. However, no responsibility is assumed by Tyco Video Systems for its use, nor any infringements of other rights of third parties which may result from its use. No license is granted by implications or otherwise under any patent rights of Tyco Video Systems.