

VIDEO SYSTEMS

Adding Intelligence to Video

TECHNICAL BULLETIN

Date: 10/29/02
Subject: Intellex 2.X, Accessing CD-RW

Technical Bulletin TB_102902

Purpose: This bulletin identifies two work around solutions for Intellex's with two or more ESM that are unable to access CD-RW drives.

Issue: A problem exists that prevents Intellex from accessing the CD-RW drive when more than one ESM is connected. This same problem exists in Intellex software version 2.2, 2.3 and 2.4.

Work Around Solution: Start the Intellex with the ESM modules disconnected. Then add the ESM's after the Intellex boots. This will have to be repeated if the Intellex reboots or if power fails..

Work Around Solution: Reduce the number of ESM modules connected.

Information furnished by Tyco Video Systems is believed to be accurate and reliable. However, no responsibility is assumed by Tyco Video Systems for its use, nor any infringements of other rights of third parties which may result from its use. No license is granted by implications or otherwise under any patent rights of Tyco Video Systems.