



TECHNICAL BULLETIN

Date: 01/22/03
Subject: Intellex 3.0, Start Up After Power Loss

Technical Bulletin TB_012203

Purpose: This bulletin identifies a situation that can potentially cause an unrecoverable condition in Intellex 3.0.

Issue: Improper shutdown of Intellex 3.0, including interrupting power, can prohibit the Intellex from starting up. This condition is particularly susceptible during power up and shutdown.

Solution: Intellex units that cannot start up will need to be returned for factory repair.

Recommendation: Following proper shutdown procedures listed in the "Users Manual" will greatly reduce the possibility of triggering an interruption of power during either start up or shutdown.

Recommendation: A UPS (Uninterrupted Power Supply) can help prevent an unanticipated power loss.

Information furnished by American Dynamics is believed to be accurate and reliable. However, no responsibility is assumed by American Dynamics for its use, nor any infringements of other rights of third parties which may result from its use. No license is granted by implications or otherwise under any patent rights of American Dynamics.