



## TECHNICAL BULLETIN

Date: 02/13/02

Technical Bulletin TB\_021302

Subject: Intellex Field Replaceable Parts List

**Purpose:** For Intellex Certified Solution Providers here is a list of Intellex field replaceable parts for ease of ordering.

DESCRIPTION DAT DRIVES	PART NUMBER	NOTES
DAT Drive, Sony DDS3*	2025-6039-01	Recommend Upgrading to DDS4 per Tech Bulletin TB_110701
Cable, SCSI, Internal	6003-0161-01	Needed to upgrade DDS3 to DDS4 drive*
DAT Drive, Sony DDS4	2025-6088-01	Needed to upgrade DDS3 to DDS4 drive*
SCSI 3 adapter	2025-0359-01	Needed to upgrade DDS3 to DDS4 drive*
Terminator, SCSI-3, Internal	2025-0309-01	Needed to upgrade DDS3 to DDS4 drive*

DESCRIPTION	PART NUMBER	NOTES
Adapter, Rack Mount, BNC Panel	0500-8264-01	
Adaptor, BNC to RCA Male	2113-0015-01	
Alarm Adapter Kit	0352-0006-01	
BNC Board	0311-0010-01	
BNC Vinyl Cap	2111-0059-01	
CABLE ASSY, 10 PIN	6003-6012-01	
Cable Assy, Alarm, 30"	6003-6038-01	
Cable Assy, External Video, 30"	6003-6036-01	
CABLE ASSY,16 PIN	6003-6006-01	
CABLE ASSY,26 PIN	6003-6007-01	
CABLE ASSY,34 PIN	6003-6028-01	
CABLE ASSY,40 PIN DATA/SYSTEM	6003-6029-01	Cable between system drive and data drive
CABLE ASSY,40 PIN,DATA	6003-6027-01	Cable between data drive and data drive
CABLE ASSY,50 PIN	6003-6030-01	
CABLE ASSY,SCSI-3,DP SERIES	6003-6031-01	
Cable, Alarm, External	6003-6034-01	
Cable, Front Panel	2025-6079-01	
Cable, IDE HDD	6003-0168-01	
Cable, Internal Video	0652-0007-01	
Cable, Ribbon, MB to VABD Reset	6003-0158-02	
Cable, Video, External	6003-6037-01	
Cable, Video, Internal	6003-6035-01	
Call Monitor Board	RDVUPGCMB	Supports advance Call Monitor features.
Call Monitor Board, Unpopulated	0301-1096-02	Does not support advance Call Monitor features.
CD-ROM Drive	2025-0338-01	

Information furnished by Sensormatic is believed to be accurate and reliable. However, no responsibility is assumed by Sensormatic for its use; nor for any infringements of other rights of third parties which may result from its use. No license is granted by implications or otherwise under any patent or patent rights of Sensormatic Video Systems Division.

Technical Services Email- [vsdtechservices@tycoint.com](mailto:vsdtechservices@tycoint.com)

Tel (800) 507-6268 (International: 561-912-6259)-Option 2 • Fax (845) 624-7685

DESCRIPTION	PART NUMBER	NOTES
CD-RW Drive	RDVUPGCDRW	
CD-RW, 650MB, with Case	1390-0018-01	
Data Drive, 100G	0710-0042-0100	
Dongle, Network Client 1.0	RDVNCK-10	
Dongle, Network Client 2.0L	RDVNCK-20	Not needed for base version
FILTER,EMI,FERRITE,CLAMP,,500I	2700-0023-01	Part of Alarm Adaptor Kit, 0352-0006-01
Firewire Board	2025-0340-01	
FLOPPY DRIVE,1.44MB,3.5 INCH	2025-6016-01	
Front Cover Door	2025-6081-01	
Front Panel Board	2025-6078-01	
Hard Drive, Data, 60GB	0701-2699-0100	
Hard Drive, System, 60GB	0701-2698-0100	
HDD, 60GB, System, NTLX 2.1 b19	RDVUPG30C	
HDD, 60GB, System, NTLX 2.2 b16	0701-2710-0102	
HDD, 80GB, Data	0710-0015-0100	
HDD, 80GB, System, NTLX 2.1 b19	0710-0014-0101	
Modem Board, 56K, Internal, ISA	RDVUPGM2	
Modem Board, 56K, Internal, PCI	RDVUPGM1	
Monitor, 17" SVGA, Black	RVGA1710B	
Motherboard wCPU/Memory	0400-1006-01	Model DVL or DV16000 Motherboard
Motherboard wCPU/Memory	0404-0004-01	Model DV8000 Motherboard
Motherboard, w/CPU & Memory	0301-1092-01	Model MDV Motherboard
Mouse Pad, Intellex	0500-8266-01	
Mouse, 2 Button, Black	2025-6040-02	
Mouse, 2 Button, White	2025-6067-01	
NETWORK,INTERFACE,CARD,PCI	2025-6057-01	
OVRLY,ALARM ADAP,DV8000	2412-0070-01	Part of Alarm Adaptor Kit, 0352-0006-01
P/S,DC,250W,MODIFIED,NO,SWITC	2025-6015-01	
PCA,ALARM ADAPTER BOARD	0311-0014-01	Part of Alarm Adaptor Kit, 0352-0006-01
PCA,CPU,300MHZ,DP SERIES	2025-6063-01	
Power Cable, Europe	6003-0033-01	
Power Cable, Europe, Right Angle	6003-6000-01	
Power Cable, UK	6003-0040-01	
Power Cable, USA/Canada	6003-0007	
Power Supply, 115/220V	2025-6060-01	
Rack Mount Kit	UHRM09	
SCSI Adapter Card	2025-6071-01	
Switch Actuator Tool	0500-8267-01	
System Drive, NTLX 2.2, 100G	0710-0041-0100	
System Drive, NTLX 2.2, 80G	0710-0014-0102	
Terminator, BNC	2113-0022-01	
Terminator, SCSI-3, External	2025-6065-01	
VACD Board (TM1300)	0301-1101-01	
VACD Daughter Board	0301-1077-01	
Video Card, 32M, NTSC/PAL	2025-0334-01	
Video Card, AGP, NTSC	2025-6087-01	
Video Card, AGP, PAL	2025-6089-01	

Information furnished by Sensormatic is believed to be accurate and reliable. However, no responsibility is assumed by Sensormatic for its use; nor for any infringements of other rights of third parties which may result from its use. No license is granted by implications or otherwise under any patent or patent rights of Sensormatic Video Systems Division.

Technical Services Email- [vsdtechservices@tycoint.com](mailto:vsdtechservices@tycoint.com)

Tel (800) 507-6268 (International: 561-912-6259)-Option 2 • Fax (845) 624-7685

DESCRIPTION (RDV Models)	PART NUMBER	NOTES
PCA,FRNT PNL CNTRL	0301-1015-01	Spares are available but end of life.
PCA,ANALOG,NTSC	0301-1020-01	Spares are available but end of life.
PCA, BNC/ALARM,16 CAM	0301-1021-01	Spares are available but end of life.
PCA,BNC/ALARM,9 CAM	0301-1025-01	Spares are available but end of life.
PCA,ANALOG,PAL	0301-1029-01	Spares are available but end of life.
PCA,LIVE DISPLAY/TOOL	0301-1031-01	Spares are available but end of life.
PCA, COMPRESSOR	0301-1039-01	Spares are available but end of life.

Information furnished by Sensormatic is believed to be accurate and reliable. However, no responsibility is assumed by Sensormatic for its use; nor for any infringements of other rights of third parties which may result from its use. No license is granted by implications or otherwise under any patent or patent rights of Sensormatic Video Systems Division.

Technical Services Email- [ysdtechservices@tycoint.com](mailto:ysdtechservices@tycoint.com)

Tel (800) 507-6268 (International: 561-912-6259)-Option 2 • Fax (845) 624-7685